

## PRODUCT IDENTIFICATION GUIDE | MODEL MI3050S

**1 COMPARE YOUR SMOKE ALARM** to the product images below. Affected smoke alarms are identical to the image with the red alert symbol. All other alarms are not affected by this product notice.

Verify your smoke alarm is manufactured by Universal Security Instruments:



Model MI3050S

**MAY BE AFFECTED**



**2 PRESS THE TEST BUTTON**

- If the alarm **sounds**, no further action is necessary.



Universal Security Instruments encourages everyone to test their alarms weekly, by pressing the test button, and to clean their alarms monthly, to ensure proper operation.

- If the alarm **does not sound**, remove it from the mounting bracket by twisting it counter clockwise.
- See **Step 3** for further instructions.


PRODUCT IDENTIFICATION GUIDE | MODEL MI3050S

**3** LOCATE THESE MARKINGS ON THE BACK OF YOUR ALARM.

**Company Name:**  
Universal Security Instruments  
USI Electric models are not involved

**Model Number:**  
MI3050S

**Date Manufactured:**  
2015JAN19 through 2016JUL11



**4** IF YOUR ALARM IS AFFECTED contact us:  
<https://www.universalsecurity.com/reg-form/>  
[safety@universalsecurity.com](mailto:safety@universalsecurity.com)  
(877) 612.6955

**5** IF YOUR ALARM IS **NOT** AFFECTED no further action is needed.



Universal Security Instruments encourages everyone to test their alarms weekly, by pressing the test button, and to clean their alarms monthly, to ensure proper operation.